



# Material depending form filling

Deviations due to material and batch fluctuations \*



aXw Control RecyclatePilot compensates for material and batch fluctuations\*



\* Without holding pressure, PA6 Ultramid, without sprue

■ regrind    ■ recyclate    ■ virgin material